

24. Mrz. 15

<u>File No</u>	<u>Client</u>	<u>City</u>	<u>Country</u>	<u>End User</u>	<u>Location</u>	<u>Type</u>	<u>Pcs</u>	<u>Size</u>	<u>Model</u>	<u>Slurry</u>
1979.301.224	Lurgi	Frankfort	D	Ford-Werke AG, Saarlouis	Germany	KFP	1	1200x1200	021.73/319/665/LVE/AK	Effluent from automobile industry and cathodic electrophoresis
1981.04.7253	Air Industrie		F	Renault Sand.	France	KFP	1	630x630	021.43	not known
1984.04.5463	Heuliez		F	Euroautomobiles	France	KFP	1	800x800	021.53	not known
1984.201.118	Netzsch Inc.	Lionville	USA	Chrysler Corp. Detroit + Newark	USA	KFP	2	1200x1200	021.73/319/665/LVE/AK	Effluent pre-treatment
1984.601.069	Wabag	Kulmbach	D	VW Wolfsburg	Germany	MKFP	1	1500x1500	021.83/319/665/LVE/314	Wet deslagging effluents
1984.701.301	Daimler Benz	Stuttgart	D	Factory Haedelfingen	Germany	KFP	1	1000x1000	510.63/319/595/LVE	Metal hydroxide sludge
1984.701.305	Dürr	Stuttgart	D	Opel	Germany	KFP	1	800x800	021.53/319/665/LVE	Effluent from enamelling line
1985.04.5683	Automobiles Citroen		F	see client	France	KFP	1	630x630	021.43	not known
1985.501.962	Degrement Benelux S.A.	Herstal	B	Renault Industrie, Vilvorde	Belgium	KFP	1	800x800	021.53/319/665/LVE	not known
1985.701.322	Alfa-Laval	Kloten	CH	AMAG Automobil- und Motoren AG, Birrfelden	Switzerland	KFP	1	800x800	021.53/264 MPA	Hydroxide sludge
1985.701.324	Eisenmann	Böblingen	D	Ford-Werke AG, Köln	Germany	KFP	1	800x800	021.53/319/665/LVE	Thin sludge containing zinc phosphate
1985.701.344	Dürr	Stuttgart	D	Adam Opel AG, Bochum	Germany	KFP	1	800x800	021.53/319/665/LVE	not known

<u>File No</u>	<u>Client</u>	<u>City</u>	<u>Country</u>	<u>End User</u>	<u>Location</u>	<u>Type</u>	<u>Pcs</u>	<u>Size</u>	<u>Model</u>	<u>Slurry</u>
1985.701.345	Dürr	Stuttgart	D	General Motors, Antwerpen	Belgium	KFP	1	800x800	021.53/319/665/LVE/AK	Effluent from spraying booths
1986.04.6000	Büttner		F	Peugeot Mulhouse	France	KFP	1	800x800	021.53	not known
1986.04.6041	Lurgi		F	Ford	France	KFP	1	1000x1000	021.63	not known
1986.201.680	Otomarsan A.S.	Istanbul	TR	Mercedes Benz Türk A.S., Aksaray	Turkey	KFP	1	800x800	021.53/319/2H	Metal hydroxide sludge
1986.301.474	Thyssen Wassertechnik	Mannheim	D	BMW, Dingolfing	Germany	KFP	1	1000x1000	021.63/319/665/LVE/AK	Metal hydroxide sludge
1986.440.007	Deutsche Babcock AG	Krefeld	D	Audi, Neckarsulm	Germany	KFP	1	1200x1200	021.73/319/665/LVE/314	Production effluents: Hydroxide- or carbonate sludge
1986.701.383	Dürr	Stuttgart	D	BMW, Regensburg	Germany	KFP	2	1000x1000	021.63/319/665/LVE/AK	not known
1987.040.185	Eisenmann	Böblingen	D	VW Mexiko	Mexico	KFP	1	800x800	021.53/264 MPA	Zinc phosphate sludge
1987.340.060	Lurgi GmbH	Frankfort	D	VW Mexiko	Mexico	KFP	2	800x800	021.53/264 MPA	Waste water from automobile factory
1987.740.014	Eisenmann	Böblingen	D	VW AG Works Hannover	Germany	KFP	2	800x800	021.53/319/665/LVE	Metal hydroxide sludge
1990.040.630	Skoda Export	Prague	CZ	see client	Czech Republic	KFP	1	800x800	021.53/319/665/LVE	not known
1990.340.156	ABB Flaekt	Butzbach	D	Ford, Genk	Belgium	KFP	1	630x630	021.43/319/665/LVE	Phosphate sludge
1990.540.091	General Motors	Antwerp	B	Opel Belgium N.V., Antwerpen	Belgium	KFP	1	1000x1000	021.63/319/665/LVB	Metal hydroxide sludge
1990.740.136	Dürr	Stuttgart	D	Ford-Werke, Köln	Germany	KFP	1	800x800	021.53/319/665/LVE	not known
1990.740.147	Dürr	Stuttgart	D	BMW Landshut	Germany	KFP	1	630x630	021.43/319/665/LVE	not known

<u>File No</u>	<u>Client</u>	<u>City</u>	<u>Country</u>	<u>End User</u>	<u>Location</u>	<u>Type</u>	<u>Pcs</u>	<u>Size</u>	<u>Model</u>	<u>Slurry</u>
1990.740.149	Eisenmann	Böblingen	D	Opel AG, Ruesselsheim	Germany	KFP	1	800x800	021.53/319/665/LVE	not known
1990.840.051	Siedentop	Gifhorn	D	Otec Oberflächen- technik, Düren	Germany	KFP	1	400x400	021.14/264 MPA	Neutralized thin sludge
1990.840.058	Siedentop	Gifhorn	D	Kaessbohrer Fahrzeugw., Dortm.	Germany	KFP	1	400x400	021.14/264 MPA	Neutralized thin sludge
1990.940.089	GNL	Linz	A	Steyr-Daimler-Puch	Austria	KFP	1	400x400	021.14/264 MPA-E	Phosphate sludge
1991.340.207	Opel AG	Rüsselsheim	D	see client	Germany	KFP	2	800x800	021.53/319/665/LVE	not known
1991.740.176	Dürr	Stuttgart	D	VW Sachsen, Mosel	Germany	KFP	1	630x630	021.43/264 MPA	not known
1991.740.185	Eisenmann	Böblingen	D	BMW Muenchen	Germany	KFP	1	630x630	021.43/319/665/LVE	not known
1991.740.187	Dürr	Stuttgart	D	Saab	Finland	KFP	1	630x630	021.43/319/665/LVE	not known
1991.740.202	Dürr	Stuttgart	D	Saipa Co., Teheran	Iran	KFP	1	630x630	021.43/264 MPA	Effluent from pre-treatment of automobile chassis
1991.740.205	Dürr	Stuttgart	D	Saab	Finland	KFP	1	630x630	021.43/319/665/LVE	not known
1991.840.067	VW	Wolfsburg	D	VW Werk Mosel, Zwickau	Germany	KFP	1	1500x1500	021.83/319/665/LVE	not known
1991.870.035	Bloem & Janssen	Südbrookmer- land	D	VW Emden	Germany	KFP	1	1200x1200	021.73/319/665/LVE	Effluent from factory's sewage treatment plant
1992.040.016	Werkstatt- Technik	Cham	D	see client	Germany	KFP	1	470x470	021.24/264 HP	Sludge from oil separator
1992.440.141	Kramer GmbH	Bergheim- Quadrath	D	Ford-Werke Saarlouis	Germany	KFP	1	630x630	021.43/319/665/LVE	Effluent from phosphating plant
1992.740.265	Dürr	Stuttgart	D	Mercedes Benz, Sindelfingen	Germany	KFP	1	630x630	021.43/264 MPA	Activated sludge from biological water treatment

<u>File No</u>	<u>Client</u>	<u>City</u>	<u>Country</u>	<u>End User</u>	<u>Location</u>	<u>Type</u>	<u>Pcs</u>	<u>Size</u>	<u>Model</u>	<u>Slurry</u>
1992.870.057	Mercedes-Benz	Hamburg	D	see client	Germany	KFP	1	470x470	021.24/264 MPA-E	Cataphoresis sludge, zinc phosphate
1993.040.431	Nutzfahrzeuge Ludwigsfelde	Ludwigsfelde	D	Mercedes Benz AG, NLG, Ludwigsfelde	Germany	KFP	1	630x630	021.43/319/668/LVE	Industrial effluent
1993.440.175	AW Electronic	Mülheim/Ruhr	D	osmo Holz und Color GmbH, Warendorf	Germany	KFP	1	470x470	021.24/264 HP	Hydroxide sludge
1993.870.064	WAT GmbH	Norderstedt	D	VW Hannover	Germany	KFP	1	400x400	021.14/264 HP	Leakage water treatment
1994.040.577	MTM	Milan	I	FISIA - FIAT, Bielsko Biala	Poland	KFP	1	800x800	021.53/319/668/LVE	Neutralized effluent sludge from the metal industry
1994.040.663	Rockinger	Munich	D	see client	Germany	KFP	1	250x250	021.04/264 HP	Zinc phosphate solution
1994.340.313	ABB Oberflächen-technik	Butzbach	D	Daimler Chrysler Ludwigsfelde GmbH	Germany	KFP	1	400x400	021.14/264 MPA-E	Thickened sludge from phophating plant
1995.040.740	Durr Limited	Warwick	GB	Vauxhall Motors Ltd.	Great Britain	KFP	1	800x800	021.53/319/668/LVE	Water paint sludge from automobile spraying booths
1995.040.841	Widmer & Ernst	Bad Hersfeld	D	VW Hannover	Germany	KFP	1	800x800	021.53/319/668/LVE	Neutralized iron hydroxide sludge
1995.040.842	Widmer & Ernst	Bad Hersfeld	D	VW Hannover	Germany	KFP	1	630x630	021.43/319/668/LVE	Coagulated KTL-lacquer
1996.040.036	VMB	Babenhausen	D	FTE automotive GmbH, Ebern	Germany	KFP	1	400x400	021.14/264 HP	Saline thin sludge from deburring plants
1996.040.066	GTI Technical Installations nv	Lochristi	B	Volvo Cars Europe, Gent	Belgium	MKFP	1	800x800	021.53/319/668/LVB/AK	Paint and biological sludge, mixed at 50 % each
1996.040.075	Saipa Co.	Tehran	IRAN	see client	Iran	KFP	1	630x630	021.43/264 MPA-E	Effluent from pre-treatment of automobile chassis

<u>File No</u>	<u>Client</u>	<u>City</u>	<u>Country</u>	<u>End User</u>	<u>Location</u>	<u>Type</u>	<u>Pcs</u>	<u>Size</u>	<u>Model</u>	<u>Slurry</u>
1996.040.076	ABB Flexible Automation GmbH	Butzbach	D	Mercedes Benz Nutzfahrzeuge Ludwigsfelde	Germany	KFP	1	630x630	021.43/319/668/TM/AK	Phosphate sludge, pH-value: < 5
1997.40.000.248	Eisenmann	Böblingen	D	Daewoo Avia, J.S.C., Prag	Czech Republic	KFP	1	470x470	021.24/264 MPA-E	not known
1997.40.000.249	Eisenmann	Böblingen	D	Daewoo Avia, J.S.C., Prag	Czech Republic	KFP	1	470x470	021.24/264 MPA-E	not known
1997.40.001.070	Dürr	Stuttgart	D	General Motors	China	KFP	1	630x630	021.43/319/668/LVE	Thin sludge containing metal hydroxide
1998.201.14a	Durr India	Chennai	IND	Ford India Ltd., Maraimalainagar	India	KFP	1	800x800	021.53/264 MPA	Paint shop effluent
1998.201.14b	Durr India	Chennai	IND	Ford India Ltd., Maraimalainagar	India	KFP	1	800x800	021.53/264 MPA	Biological slurry
1998.40.001.126	Dürr	Stuttgart	D	VW do Brasil for Audi do Brasil	Brazil	KFP	1	800x800	021.53-15/319/668/LVE/AK	Effluent from enamelling line
1998.40.001.152	Baur GmbH	Reutlingen	D	Dürr - Project Mercedes Benz, Bremen	Germany	KFP	1	470x470	021.24/264 MPA-E	Effluent from pyrolysis with 2 g/l chloride, particles 90 % < 10 µm
1998.40.001.163	Dürr	Stuttgart	D	VW Audi Brazil	Brazil	KFP	1	800x800	021.53/319/668/LVE/AK	Paints, dyestuffs
1998.40.001.189	Dürr	Stuttgart	D	General Motors, Antwerpen	Belgium	KFP	1	800x800	021.53-15/319/668/LVE/AK/314	Phosphate slurry
1998.40.001.195	FTE Automotive GmbH	Ebern	D	see client	Germany	KFP	1	470x470	021.24/264 HP	not defined
1998.40.001.203	VMB	Babenhausen	D	Skoda	Czech Republic	KFP	1	400x400	021.14/264 HP	Saline thin sludge from deburring plants
1998.40.001.204	OSMO-Anlagenbau GmbH	Georgsmarienhütte	D	Adam Opel AG, Bochum	Germany	KFP	1	630x630	021.43/264 MPA-E	Flotation slurry

<u>File No</u>	<u>Client</u>	<u>City</u>	<u>Country</u>	<u>End User</u>	<u>Location</u>	<u>Type</u>	<u>Pcs</u>	<u>Size</u>	<u>Model</u>	<u>Slurry</u>
1998.40.001.312	Sterling Berkefeld	Celle	D	VW Poznan	Poland	KFP	1	470x470	021.24/264 MP/AE/AP	not known
1998.94.001.011	GNL	Linz	A	Mitsubishi Heavy Industries	Japan	KFP	1	800x800	021.53-15/319/668/LVE/AK	SiO2-Slurry
1999.40.001.370	Dürr	Stuttgart	D	Volkswagen Slovakia A.S., Bratislava	Slovakia	KFP	2	800x800	021.53-15/319/668/LVE/AK	Effluents from paint shop
1999.40.001.399	VMB	Babenhausen	D	Saab	Sweden	KFP	1	400x400	021.14/264 HP/AP	Saline thin sludge from deburring plants
1999.40.001.493	Dürr	Stuttgart	D	Daimler-Chrysler, Ludwigsfelde	Germany	KFP	1	800x800	021.53/319/668/LVE/AK/FAA-O	Thin sludge containing metal hydroxide, pH 6,5-10
1999.40.001.498	IAM Industrieanlagen-Montage GmbH	Neuss	D	Audi AG, Ingolstadt	Germany	KFP	1	630x630	021.43/264 MP/AE/AP	Flushing water, pH 2-3
1999.40.001.526	Volkswagen AG	Wolfsburg	D	Works Zwickau	Germany	KFP	1	1000x1000	021.63-15/319/668/LVE/KAV-K/AV/AK/314	not known
1999.40.001.544	HLS GalvanoTechnik Leipzig GmbH	Lindenthal / Leipzig	D	Fahrzeugtechnik Ebern	Germany	KFP	1	470x470	021.24/264 MP/AE/AP	Effluent
1999.40.001.552	VMB	Babenhausen	D	Opel	Germany	KFP	1	470x470	021.24/264 HP/AP	Saline thin sludge from deburring plants
2000.40.001.665	Dürr Systems GmbH	Stuttgart	D	Opel Rüsselsheim	Germany	KFP	1	800x800	021.53-15/319/668/LVB/AK/FAA-G	Phosphate sludge (phosphoric acid)
2000.40.001.685	China Timeking Intl. Economic Coop. & Trade Co.	Beijing	PRC	see client	China	KFP	2	800x800	021.53-8/MPA-P/AP	Sludge from painting shop of automobile manufacturer General Motors

<u>File No</u>	<u>Client</u>	<u>City</u>	<u>Country</u>	<u>End User</u>	<u>Location</u>	<u>Type</u>	<u>Pcs</u>	<u>Size</u>	<u>Model</u>	<u>Slurry</u>
2000.40.001.734	Preussag Wassertechnik GmbH	Achim	D	VW Braunschweig	Germany	KFP	1	470x470	021.24/264 MPA-E	Dyestuff effluent
2000.40.001.747	VMB	Babenhausen	D	Volkswagen	Argentina	KFP	1	470x470	021.24/264 HP/AP	Saline thin sludge from deburring plants
2000.40.001.774	ABB Paint Automation GmbH	Butzbach	D	BMW München	Germany	MKFP	2	800x800	021.53-16/319/668/LVE/AK	Phosphate slurry (direct filtration of phosphating zone)
2000.40.001.779	ABB Paint Automation GmbH	Butzbach	D	BMW Dingolfing	Germany	MKFP	4	800x800	021.53-16/319/668/LVE/AK	Phosphate slurry (direct filtration of phosphating zone)
2001.40.001.839	RR Navigare Im- + Export GmbH	Weyhe / Bremen	D	Project Hyundai	Sri Lanka	KFP	1	250x250	021.04/264 HP/AP	not known
2001.40.001.845	Langbein & Engelbracht GmbH	Bochum	D	VW, Hannover	Germany	KFP	1	400x400	021.14/264 HP/AP	Laquer slurry
2001.40.001.975	Shanghai Automobile Imp. & Exp. Corp.	Shanghai	PRC	Shanghai General Motor	China	KFP	1	630x630	021.43/264 MPA-E/AP	not known
2001.40.002.015	Montgomery Watson China Con. Ltd.	Shanghai	PRC	Nichia Shanghai Corporation	China	MKFP	1	630x630	021.43/319/668/TM/AP	not known
2001.94.001.052	GNL	Linz	A	MAGNA Steyr Fahrzeugtechnik, Graz	Austria	KFP	1	800x800	021.53/319/668/LVE/AK	Iron hydroxide slurry
2002.40.002.058	SHANGHAI Materials & Equipment Group	Shanghai	PRC	VW Shanghai	China	KFP	1	800x800	021.53/319/668/TM/AP	Slurry from car painting

<u>File No</u>	<u>Client</u>	<u>City</u>	<u>Country</u>	<u>End User</u>	<u>Location</u>	<u>Type</u>	<u>Pcs</u>	<u>Size</u>	<u>Model</u>	<u>Slurry</u>
2002.40.002.060	SHANGHAI Materials & Equipment Group	Shanghai	PRC	VW Shanghai	China	KFP	1	800x800	021.53/319/668/TM/AP	Slurry from car painting
2002.40.002.089	Seprotech (Pty.) Ltd.	Kempton Park	ZA	VATECH WABAG SA (Pty.) Ltd. / BMW Rosslyn Plant	South Africa	KFP	1	470x470	021.24/264 HP	Effluent from paint shop
2002.40.002.090	Seprotech (Pty.) Ltd.	Kempton Park	ZA	VATECH WABAG SA (Pty.) Ltd. / BMW Rosslyn Plant	South Africa	KFP	1	470x470	021.24/264 HP	Effluent from paint shop
2002.40.002.119	NETZSCH Korea Co. Ltd.	Koyang	ROK	Taikisha Korea Ltd. - Hyundai	South Korea	KFP	1	470x470	021.24/264 MPA-E/AP	Phosphoric acid in automobile production
2002.40.002.136	Eisenmann Maschinenbau KG	Böblingen	D	Volvo Cars, Gent	Belgium	MKFP	3	800x800	021.53- 15/319/668/LVE/AK	Thin slurry from zinc, phosphating with max. 30 % aluminium, Temp. 60°C, ph Wert 3
2003.40.002.208	WITH US nv-sa	Ternat	B	Volvo Cars, Gent	Belgium	MKFP	1	1200x1200	021.73-15/319/668/ LVB/AK/314	Slurry from physical-chemical effluent treatment, pH ca. 7
2003.40.002.213	Eisenmann Maschinenbau KG	Böblingen	D	BMW Leipzig	Germany	MKFP	2	800x800	021.53- 15/319/668/LVE/AK	Zinc phosphating bath with max. 30 % aluminium content
2003.40.002.214	Eisenmann Maschinenbau KG	Böblingen	D	BMW Leipzig	Germany	KFP	1	800x800	021.53- 15/319/668/LVE/AK	Metal hydroxide slurry from physical-chemical plant, pH value 7
2003.40.002.215	Eisenmann Maschinenbau KG	Böblingen	D	BMW Leipzig	Germany	KFP	1	800x800	021.53- 15/319/668/LVE/AK	Metal hydroxide slurry from waste water plant (nitrite slurry), pH value 7
2003.40.002.216	Eisenmann Maschinenbau KG	Böblingen	D	BMW Regensburg	Germany	MKFP	2	800x800	021.53- 15/319/668/LVE/AK	Zinc phosphating bath with max. 30 % aluminium content

<u>File No</u>	<u>Client</u>	<u>City</u>	<u>Country</u>	<u>End User</u>	<u>Location</u>	<u>Type</u>	<u>Pcs</u>	<u>Size</u>	<u>Model</u>	<u>Slurry</u>
2004.40.002.311	Shanghai Baosteel Intl. Economic & Trading Co. Ltd	Shanghai	PRC	General Motors	China	KFP	1	800x800	021.53/319/668/TM/AP	Slurry from automotive painting
2004.40.002.312	Shanghai Baosteel Intl. Economic & Trading Co. Ltd	Shanghai	PRC	General Motors	China	KFP	1	800x800	021.53/319/668/TM/AP	Slurry from automotive painting
2004.40.002.335	RMT Rohr- und Maschinenanlage ntechnik GmbH	Oldenburg	D	Audi Ingolstadt	Germany	KFP	1	800x800	021.53/319/668/LVE/SG/AK	Slurry from nickel precipitation
2004.40.002.379	Shanghai Baosteel Intl. Economic & Trading Co. Ltd	Shanghai	PRC	Project Yike - Daewoo	China	KFP	1	630x630	021.43/319/668/TM/AP	Sludge from motorcar painting
2004.40.002.420	DE.ENCON GmbH	Oldenburg	D	Project Audi Ingolstadt	Germany	KFP	1	630x630	021.43/319/668/LVE/AK	Paint slurry containing aluminium hydroxide
2005.40.002.515	BMW AG	Munich	D	Works Regensburg	Germany	KFP	1	800x800	021.53/319/668/LVE/AK	Effluents from paint shop
2006.40.002.570	Eisenmann Maschinenbau GmbH & Co. KG	Böblingen	D	DC Mettingen	Germany	KFP	2	630x630	SE630CRD	Thin sludge from zinc phosphate bath
2006.40.002.572	Eisenmann Maschinenbau GmbH & Co. KG	Böblingen	D	DC Mettingen	Germany	KFP	1	470x470	SE470CD	Thin sludge from zinc phosphate bath, KTL effluent containing paint
2006.40002485	Jilin Province Sunrise Economy & Trade Co. Ltd.	Chang Chun	PRC	Shenyang HuaCheng Cold Cup	China	KFP	1	800x800	SE800CD	Sludge from automobile plant
2008.40008974	FTE automotive Czechia s.r.o.	Podborany	CZ	see client	Czech Republic	KFP	1	470x470	SH470CD	Saline thin sludge from deburring plants

<u>File No</u>	<u>Client</u>	<u>City</u>	<u>Country</u>	<u>End User</u>	<u>Location</u>	<u>Type</u>	<u>Pcs</u>	<u>Size</u>	<u>Model</u>	<u>Slurry</u>
2008.40009239	Shanghai General Motors Corp. Ltd.	Shanghai	PRC	see client	China	KFP	1	630x630	SE630CD	Neutralized hydroxide effluent from automotive production
2009.40012947	IAM Industrieanlagen montage GmbH	Kaarst-Holzbüttgen	D	Audi Ingolstadt	Germany	KFP	1	470x470	SE470CD	Wastewater from automobile industry (composition unknown)
2010.40015680-1	Eisenmann Anlagenbau GmbH & Co. KG	Böblingen	D	Volkswagen Slovakia A.S., Bratislava	Slovakia	KFP	1	800x800	SE800CRD	Zinc phosphate slurry
2010.40015680-2	Eisenmann Anlagenbau GmbH & Co. KG	Böblingen	D	Volkswagen Slovakia A.S., Bratislava	Slovakia	KFP	2	800x800	SE800CRD	Metal hydroxide thin slurry
2011.40018525	Eisenmann Anlagenbau GmbH & Co. KG	Böblingen	D	Volkswagen Slovakia A.S., Bratislava	Slovakia	KFP	1	470x470	SE470CD	Lacquer sludge containing traces of release agents (butylglycol), T max. 40 °C
2012.40023102	De.Encon GmbH	Oldenburg	D	AUDI Hungaria Motor KFT, Győr	Hungary	KFP	1	800x800	SE800CRD	Sludge from wastewater treatment plant
2012.40023856	Umicore Autocad France SAS	Florange	F	see client	France	KFP	1	630x630	SE630CD	Sludge from production of automotive catalysts
2012.40025358	Robert Bosch GmbH	Bamberg	D	Werkteil 4, Bau 402/0 Nordseite, Am Börstig 2, Bamberg	Germany	KFP	1	800x800	SE800CRD	Hydroxide sludge with paint effluent
2012.40025785	Andritz AG	Graz	A	Magna Steyr Fahrzeugtechnik, Graz	Austria	KFP	1	800x800	SE800CR	Metal hydroxide sludge
2013.40029221	Umicore AG & Co. KG	Hanau	D	Project India	India	KFP	1	630x630	SE630CD	Sludge from production of automotive catalysts

<u>File No</u>	<u>Client</u>	<u>City</u>	<u>Country</u>	<u>End User</u>	<u>Location</u>	<u>Type</u>	<u>Pcs</u>	<u>Size</u>	<u>Model</u>	<u>Slurry</u>
2014.40035033	Eisenmann Anlaenbau GmbH & Co. KG	Böblingen	D	Project FIASA (Fiat Betim)	Brazil	KFP	2	800x800	SE800CRD	Zinc phosphate sludge, T= max. 60 °C, DS in sludge 1.5 %
<u>Total:</u>							138			